

Oil Field Environmental Incident Summary

Incident: 20160222105228 **Date/Time of Notice:** 02/22/2016 10:52

Responsible Party: Wise Services Inc

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: SORENSON SWD #1

Field Name: UNION CENTER

Well File #: 90250

Date Incident: 2/22/2016 **Time Incident:** 09:15

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 96

Sec: 14

Qtr:

Location Description:

Submitted By: Chris Applebee

Received By:

Contact Person: Scott Steckler
PO Box 2132
Watford City, ND 58854

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	4	Barrels	4	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Soaked up fluid with vac-truck and diapers/pads. Have a grader coming to dig up soil and will be disposed of properly.

Wastes Disposal Location: The contaminated dirt will be on our pad and sent to the appropriate landfill. Diapers will be placed in filter dumpster and sent to landfill.

Agencies Involved:

Updates

Date: 2/22/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.